


5200EC 1/4" MEDIUM DIE GRINDER

EXPLODED VIEW



PARTS LIST — FOR REFERENCE ONLY

Index Number	Part Number	Description	Qty.	Index Number	Part Number	Description	Qty.
1	4001001	Plug Screw	1	17	4001017	Steel Plate	1
2	4001002	O-Ring	1	18	4001018	Bearing	1
3	4001003	O-Ring	1	19	4001019	Bearing Plate	4
4	4001004	Air Regulator	1	20	4001020	Ball	1
5	4001005	Valve Spring	1	21	4001021	Rotor Blade	4
6	4001006	O-Ring	1	22	4001022	Rotor	1
7	4001007	Valve Stem	1	23	4001023	Cylinder	1
8	4001008	O-Ring	1	24	4001024	Bearing Plate	1
9	4001009	Motor Housing	1	25	4001025	Bearing	1
10	4001010	Valve Bushing	1	26	4001026	Washer	1
11	4001011	O-Ring	1	27	4001027	Spindle	1
12	4001012	O-Ring	1	28	4001028	Lock Ring	1
13	4001013	Muffler	1	29	4001029	Housing Cap	1
14	4001014	Air Inlet	1	30	4001030	Collect	1
15	4001015	Lever	1	31	4001031	Collect Nut	1
16	4001016	Lever Pin	1	32	4001032	Wrench	2



10000 SE PINE STREET
 PORTLAND, OR 97216
 503-254-1749
 FAX 503-256-4026

When ordering spare parts, please specify
 tool type, part number and description.

FOOTNOTES